



Summerfield Townhouse HOA #5

Board of Directors Meeting:
Maintenance Report
March 11, 2025
Time: 4:00 PM

9460 Rafter tail on west side of unit was reported as rotten. The rot was cut away and replaced.

9540 Rafter tail on north side of unit was reported as rotten. The rot was cut away and replaced.

Larry Blanchard

VP Building Maintenance